

PHOTO DOCUMENTATION

The House



Right side of porch, showing signs of wood deterioration.



Porch deck boards showing wear.



Porch deck boards showing wear.



Left side of porch, showing signs of wood deterioration.



Back stoop, notice the corner showing signs of wood deterioration.



Back stoop, notice the corner showing signs of wood deterioration (close-up).



The shutters are the primary defense for each of the windows in the JKH. As you can see they take a real beating from the elements. The wood simply dries out and hardware fails leaving them flopping in the wind. This causes damage to the windows.



View of the wall between the kitchen & dining room windows, just above the ac unit, showing signs of wood deterioration.



This photo shows the deterioration of the windows sashes and the loss of glazing needed to hold the panes in place.

The Cook House



View of the Cook House, we are working with a tree removal company to trim back the limbs over the top of the Cook House.



Notice the deterioration of the fascia and soffit, evidence of water running down the rafter, pooling in the soffit.



Advanced deterioration of the fascia and soffit.



Advanced deterioration of the fascia and soffit (close-up).



Notice the deterioration of the siding along the bead edge.



Cook house wall/chimney - showing signs of deterioration and needing paint.



View of the Cook House roof from inside. Middle left side, notice the 5 holes.



View of the Cook House roof from inside. Middle left side, notice the large hole hidden by a rafter in the previous photo.



*View of the Cook House roof from inside.
Front, left side along the wall, notice three
holes.*




*View of the Cook House roof from inside.
Front, left side from gable down, notice 10
holes in the roof.*


The Corn Crib



Side view of the Corn Crib roof, notice the deterioration of the shake shingles.



Interior roof of the Corn Crib, notice the complete deterioration of the ridgeline of the roof.



*Notice the separation in the rafters and the deterioration of the
ridgeline of the roof.*